# Fork/Slot: SR21

## Micro-processor Based Slot Sensors For Labeling & Packaging





- High 25kHz switching frequency
- Red/green light models
- Detection of semi-transparent labels
- Detection of registration marks on semitransparent labels
- 4-wire independent NPN and PNP output


The SR21 series slot sensors, with a 2mm slot width, provide a 12-bit (4096 step) resolution, a 20 $\mu$ s response time and a switching frequency of 25kHz.


The setting of the switching threshold is carried-out by simply pressing a button, or dynamically during label (or other reference) movement.


The SR21-RG model with double red or green light is ideal for print registration mark detection on transparent films for automatic packaging.

# IDEC


#### **Dimensions (mm)**













PLCs

**Operator Interfaces** 

**Automation Software** 

#### **Specifications**

		SR21-RG
Power Supply	10 - 30V DC, reverse polarity protection	√
Current Draw	55mA max.	
Light Emission	Red 635nm/green LED 535nm	$\checkmark$
Resolution	0.5mm	$\checkmark$
Slot Width	2mm	$\checkmark$
Slot Depth	50mm	
Detection Point Depth	7.5mm	
Setting	AUTO SET push-button	
Indicators	Yellow OUTPUT LED	
Indicators	Green/red dual color READY/ERROR LED	
Output Type	NPN and PNP	
Saturation Voltage	2V max.	
Output Current	100mA max., short-circuit protection	
Response Time	20µs max.	
Switching Frequency	25kHz	$\checkmark$
Operating Mode	e Dark/light configurable	
Connection	M8 4-pole connector	
Electrical Protection	Class 1	
Mechanical Protection	IP65	$\checkmark$
Housing Material	Aluminum	
Lens Material	Glass	$\checkmark$
Weight	120g max.	
Operating Temperature	-20 to +60°C	$\checkmark$
Storage Temperature	-20 to +70°C	$\checkmark$
Reference Standard	EN60947-5-2	$\checkmark$

CE

Power Supplies

#### Part Number

Function	Emission	Frequency	Part Number
	red/green	25kHz	SR21-RG

Additional models are available. Visit www.idec-ds.com for more information.

## Connector Cables (for connector model sensors)

Appearance	Type & Length	Use with	Part No.
	5m axial 4-pole M8 cable	SB21	CS-B1-02-G-05
-	5m radial 4-pole M8 cable	ShZT	CS-B2-02-G-05

For information on accessories, see page 229.

Sensors

# IDEC

# **Application Sensors**

# Accessories

#### **Brackets**

Diaokets			
Appearance	ltem	Use with	Part Number
	Mounting bracket	S60, S62,	95ACC5330 (model ST-5020)
	Mounting bracket	S65	95ACC5340 (model ST-5021)
	L shaped mounting bracket	S80	95ACC2260 (model ST-5037)

## Connector Cables (for connector model sensors)

Appearance	Type & Length	Use with	Part No.
	5m axial 4-pole M12 cable	S51, S60, S62, DS1 (emitter) AS1 (emitter)	CS-A1-02-G-05
-	5m radial 4-pole M12 cable		CS-A2-02-G-05
13	5m axial 8-pole M12 cable	S65, S80	CS-A1-06-B-05
(P)	5m axial 5-pole M12 cable	TL46, LD46, DS1 (receiver), AS1 (receiver)	CS-A1-03-G-05
A lai	5m axial 4-pole M8 cable	SR21	CS-B1-02-G-05
-	5m radial 4-pole M8 cable		CS-B2-02-G-05

#### Lenses

Appearance	Item	Use with	Part Number
	Plastic lens with 9mm focus		95ACC2540
()	Plastic lens with 18mm focus	TL46	95ACC1030
	Plastic lens with 22mm focus	1L40	95ACC1000
	Plastic lens with 28mm focus		890000194
	Plastic lens with 40mm focus	TL46, LD46	95ACC1220

Diffuse-Reflected Light Fiber Optic Unit			
Inspection Spot	Sensing Range	Use With	Part Numbers
ø 2.5 mm	10mm		SA9F-DA11
ø 5 mm	20mm	SA1J, SA1J-F	SA9F-DA12
ø 8 mm	30mm		SA9F-DA13

#### **Lens Attachments**

Description	Use With	Sensing Range	Part Number
For long range de- tection of opaque objects	SA9F-TS21	300mm	SA9Z-F11
	SA9F-TC21	200mm	
	SA9F-TM21	150mm	
	SA9F-TS21	25mm	
Sideview attach- ment	SA9F-TC21	20mm	SA9Z-F12
	SA9F-TM21	20mm	

#### **Miscellaneous Accessories**

Description	Use with		Part Number
Fiber cutter	All fiber units except heat resistant	HxLxD: 0.91" x 1.77" x 0.31" (23x 45 x 8Dmm) Included with fiber units; order replacement only	SA9Z-F01

**Operator Interfaces** 

**Automation Software** 


## 95ACC5330 (model ST-5020)


IDEC

PLCs

**Operator Interfaces** 

**Automation Software** 







3

Ø5,5

**Dimensions (mm)** 



95ACC5340 (model ST-5021)



R2

R5

40°

R10

Ø5.5


ę

10.5

1 h h i

R22

= =




**32**⁼

15°

R10

R50




ω

40°

Ø5.5

32

46



## 95ACC2260 (model ST-5037)

Ø5.5

Ø5.5




106

R73

Rmax. 2

# IDEC


# 95ACC2540 (model No. 9 PMMA)



# 95ACC1030 (model No. 18 glass)




## 95ACC1220 (model No. 40 glass)



890000194 (model No. 28 glass)


# 8810 9 21.5 25.4

#### SA9Z-F01



# Dimensions (mm)

95ACC1000 (model No. 22 glass)



PLCs

# **Laser Safety Information**

Installation: If a sensor is installed so that the laser beam may shine or reflect into the eyes of a person passing by or working in the vicinity, place an opaque sheet of material in front of the beam to prevent potential eye injury. For people working near a laser sensor, protective glasses which screen out a significant amount of the harmful radiation are recommended at all times.

All laser sensors also include a remote interlock terminal which can be used to turn the laser on or off with an external switch, as required, to operate the sensor safely from a remote location.

To avoid exposure to harmful radiation, never disassemble a laser sensor.

WARNING: Do not allow class IIIa and IIIb laser beams to shine directly into the eyes. Do not allow lasers to reflect from a glossy, shiny, or reflective surface into the eyes.

**Operator Interfaces** 





Labelling: IDEC laser sensors include CDRH-approved safety warnings shown below, in compliance with federal regulations of the Center for Devices and Radiological Health.

#### MX1C Miniature Laser Sensor:

Class Illa Laser (670nm) Visible Beam

Sensors

**Communication & Networking** 



#### All Laser Sensors:

Identification and Certification

mfd.: FEBRUARY 1997 Product conforms to 21 CFR1040



PLC

Operator Interfaces

Automation Software

**Power Supplies** 

# **General Information**

#### **Specifications**

Do not operate a sensor under any conditions exceeding these specifications.

Do not operate a sensor under current and voltage conditions other than those for which the individual sensor is rated.

Do not exceed the recommended operating temperature and humidity. Although sensors are rated for operation below 0°C, this specification does not imply that performance characteristics will remain constant under prolonged freezing conditions. Continued exposure and the accompanying frost, ice, dew, and condensation which accumulate on the optical surface will adversely affect sensor performance.

To maintain performance characteristics, do not exceed vibration and shock resistance ratings while operating a sensor. In addition, avoid impacts to the sensor housing which are severe enough to adversely affect the waterproof characteristics.

#### IEC (International Electrotechnical Commission) Ratings

Sensors rated IP67 are resistant to moisture when occasionally immersed in water. Sensors rated IP64 through IP66 are resistant to moisture when occasionally subjected to splashing or when located in the vicinity of turbulent waters. These ratings do not imply that a sensor is intended for use under continual high-pressure water spray. Avoid such applications to maintain optimal sensor performance.

Sensors rated IP64 through IP67 are dust-tight and water-tight. For best performance, avoid using any sensor in an area where it will be subjected to heavy particle blasts and where dust, water, or steam will accumulate on the optical surface.

#### Start-up

Do not test the housing for dielectric strength and insulation resistance, since the housing is connected to the electronic circuit ground of a sensor. Do not perform dielectric strength and insulation resistance tests on electrical systems without disconnecting photoelectric sensors, as such testing may result in damage to the sensor.

Several lines of sensors, as noted in the individual operation sections, are provided with an internal circuit to turn an output off for a specified amount of time upon power-up. This delay is normal; it prevents a transient state when turning power on.

#### **Optimum Performance**


The optical surface of each sensor must be cleaned on a regular basis for continual superior performance. Use a soft cloth dipped in isopropyl alcohol to remove dust and moisture build-up.

IMPORTANT: Do not use organic solvents (such as thinner, ammonia, caustic soda, or benzene) to clean any part of a sensor.

All sensors experience signal inconsistencies under the influence of inductive noise. Do not use sensors in close proximity to transformers, large inductive motors or generators. Avoid using sensors in direct contact with sources of excessive heat. Also avoid operation in close proximity to welding equipment.

# Liaht

Visible light is electromagnetic radiation with a wavelength between 390 and 770nm. White light is composed of all the visible spectrum components in equal quantity; the predominance of a specific wavelength determines the color of the light. Light Emitting Diodes (LEDs) are the most common light used in optoelectronics.



0

α

# Transmission, Absorption, Reflection

When light hits an object three things take place at the same time: reflection  $(\rho)$ , absorption  $(\alpha)$  and transmission ( $\tau$ ); with parameters and ratios that vary according to the object

themselves, which are then further differentiated by material, surface, thickness and/or color. These elements can be detected using a photoelectric sensor.

## **Extraneous Light**

Bright, extraneous light such as sunlight, incandescent lights, or fluorescent lights may impair the performance of sensors in detecting color or light.

Make sure that extraneous light does not exceed recommended levels found in the individual specifications sections. When 500 lux is specified, this is equal to 50 footcandles. The average factory illumination is ordinarily below this level, except in areas where visual inspection is being performed. Only in such brightly lit areas is incident light of particular concern.

Unwanted light interference can often be avoided simply by making sure that the optical receiver is not aimed directly toward a strong light source. When mounting direction cannot be adjusted, place a light barrier between all nearby light sources and the receiver.

#### **Through-beam Sensors**

obtain large signal differences

(when the light directly hits the

receiver and when the object

interrupts the beam) with the highest Excess Gain and the


up to 50m. These sensors can


emitter and receiver.

largest operating distance reaching



With through-beam sensors, the light emitter and receiver are contained in two different housings that are mounted one in front of the other. The light beam emitted by the emitter directly hits the receiver; each object that interrupts the beam is detected. This system is used to





operate in the harshest environmental conditions, such as in the presence of dirt or dust. The disadvantage is that two units have to be wired (an emitter and receiver). The through-beam optic function operates typically in dark mode: the output is activated when the object interrupts the beam between the

It is strongly recommended to avoid using any sensor where it will be continually subjected to elements which impair performance or cause corrosive damage to the sensor. In particular, avoid strong vibrations and shocks, corrosive gases, oils and chemicals, as well as blasts of water, steam, dust or other particles.


# **General Information**

A slit attachment is available to modify the beam size of through-beam sensors. This option is recommended for detecting very small objects (near the size of the smallest object which a sensor can detect) or for eliminating light interference when sensors are mounted in close proximity.

#### **Retro-reflective**

Photoelectric sensors with this function contain both the emitter and

I‡ receiver inside the same housing. The emitted light beam is reflected on the receiver due to a prismatic reflector; an object is detected when it interrupts the beam. Compared to the through-beam optic function, the signal difference is reduced (when the light is freely reflected by the reflector and when an object




interrupts the beam) so Excess Gain is reduced and maximum operating distances can reach 12 meters. It is necessary to operate in clean environments without dirt or dust. A retro-reflective sensor typically operates in the dark mode: output is activated when an object interrupts the light beam between the sensor and reflector.

When installing sensors which detect reflected light, make sure that unwanted light reflections from nearby surfaces, such as the floor, walls, reflective machinery or stainless steel, do not reach the optical receiver.

Also, make sure that reflected-light sensors mounted in close proximity do not cause interfering reflections. When it is not possible to maintain the recommended clearance between sensors, as noted in the individual installation sections, provide light barriers between sensors.

#### **Prismatic Reflector**

A prismatic reflector is able to reflect incident light in a parallel manner, with a reflection coefficient higher than any other object for angles less than 15°. Typically the operating distance proportionally increases according to the reflector's dimensions. The reflector can rotate the incident light's polarization plane at 90°.



#### **Polarized Retro-reflective**

In presence of critical detection of objects with very reflective surfaces, l 2 E such as shiny metals or mirrored glass, retroreflex sensors with polarized filters have to be used. In polarized retroreflex sensors, the emission light is polarized on a vertical plane, while the reception is obtained only through a polarized filter on a horizontal plane. A prismatic reflector rotates the light plane at a right angle, while the light reflected from the object maintains polarization plane unvaried and is blocked by the filter placed on the receiver. Consequently, only the light reflected by the prismatic reflector is received.

#### **Retro-reflective for Transparent Objects**



For detection of transparent objects, such as PET bottles or Mylar sheets, a low-hysteresis retro-reflective sensor (capable of detecting small signal differences) can be used. These sensors detect small

Photoelectric sensors with this function contain both the emitter and


receiver inside the same housing. The emitted light beam is reflected

signal differences that the light undergoes when it passes through a transparent object.

#### **Diffuse Proximity**



on to the receiver directly by the object. which is detected without the need of prismatic reflectors. Proximity sensors represent the most economic and fastest mounting solution. However, they work with weaker signals compared to retro-reflective sensors. Excess Gain is reduced and operating distance, depending on the object's reflection degree, can only reach 2 meters.




A proximity sensor normally operates

in light mode: the output is activated when an object enters the detection area and reflects light emitted by the sensor.

#### **Background Suppression**

Background suppression sensors allow the operator to precisely set the maximum detection distance. The operating distance adjustment is not

based upon the receiver's sensitivity, but is obtained through optic triangulation, mechanically acting on the lenses or photoelements angle or electronically using PSD (Position-Sensitive Detectors) receiving systems. Consequently the detection of an object is independent of other objects behind (or in the background), which are suppressed. Moreover, due to this adjustment method, all objects can be detected at the same distance independent of their color.




#### **Distance Sensors**



Distance sensors supply an analog signal of 0-10V or 4-20mA proportional to the measurement of the distance between the emitting optics and the target.

The main technologies involved are optic triangulation and time-of-flight. The first allows very precise measurements on short distances, while the second is ideal for medium and long distances.



Sensors

Automation Software

**Power Supplies** 

PLCs

# Sensors

# IDEC

PLC

Operator Interfaces

# Slot Sensors

A slot sensor is a version of a through-beam retro-reflective sensor,

t where the emitter and receiver are placed opposite each other on the inside of an U-shaped housing. Any target that passes through the internal slot interrupts the beam and is detected. Due to their construction, slot sensors are great for applications with short operating distances. The most typical slot sensor applications are hole or teeth detection on gears, label detection, or edge control and continuity of sheets or tapes. The emission is generally infrared light; however visible red or green




emission versions are available and able to detect references such as registration marks, that present color contrasts on transparent film.

## **Contrast Sensors**



Contrast sensors (also defined as color mark readers) present a proximity function but, instead of detecting only the presence or absence of an object, they are able to distinguish between two

surfaces. This accomplished by detecting the contrast produced by the different reflection degrees. In this manner a dark reference mark (low reflection) can be detected due to the contrast with a lighter surface (high reflection), or vice versa. In the presence of colored surfaces, the contrast is highlighted using an LED, typically red or



green. For general purposes a white light is used because the full light spectrum detects the majority of contrasts. White light emission is obtained through lamps, or LEDs in most sensors, enabling the detection of very slight contrasts due to different surface treatments, even of the same material and color.


Contrast sensors are mainly used in automatic packaging machines for registration mark detection to synchronize folding, cutting and welding.

Contrast on White Background			
Mark Color	Red LED	Green LED	White LED
Red	no	medium	medium
Orange	low	medium	medium
Yellow	low	low	medium
Green	high	no	medium
Blue	high	medium	high
Violet	medium	high	high
Brown	low	medium	high
Black	high	high	high
Gray	medium	medium	medium
White	no	no	yes

#### Luminescence Sensors

'Luminescence' is defined as visible light emission from fluorescent or phosphorous substances, due to electromagnetic radiation absorption. Luminescence sensors emit ultraviolet light, which is reflected at a

higher wavelength (minor energy) on a fluorescent surface, shifting into the visible light spectrum. Ultraviolet light emission is obtained using special lamps, or LEDs in sensors. UV emission is modulated and the visible light reception is synchronized. Maximum immunity against external interferences, such as reflections caused by very shiny surfaces, is



obtained. In addition, fluorescent targets, invisible to the human eye, can be detected. Luminescence sensors are used in various industries: detecting labels on glass or mirrors in pharmaceutical and cosmetic fields; selecting tiles marked with fluorescent marks in the ceramic industry; determining the presence of fluorescent glues on paper for automatic packaging; distinguishing cutting and sewing guides in textile manufacturing; checking fluorescent paints or lubricants in mechanical production.

incident light which are being reflected, eliminating those which have

#### **Color Sensors** The color of an object depends on all the color components of the



been absorbed. The dominant color is defined as 'hue' and depends on the reflected light's wavelength. 'Saturation' indicates the pureness of the color with respect to white and is represented as a percentage. Hue and saturation together are defined as 'chromaticity'.

Color or chromatic sensors have a proximity function with generally three RGB LEDs for light emission. The color of

blue 100% red 100%

100%

an object is identified according to the different reflection coefficients obtained with red (R), green (G) and blue (B) light emissions. More simply, yellow can be identified by R=50% G=50% B=0% reflections; orange by R=75% G=25% B=0% reflections; pink by R=50% G=0% B=0% reflections; but possible combinations are really infinite. Color sensors operate only on reflection ratios and are not influenced by light intensity, defined as 'brilliance 'or 'luminance'. There is a wide range of applications, ranging from quality and process controls, to automatic material handling for identification, orientation and selection of objects according to color.

# **Fiber Optic Sensors**




Universal functions of through-beam and proximity sensors, as well as application functions ranging from contrast and luminescence to color detection, can be obtained using fiber optic sensors. The optical fibers can be thought of as cables that transport light and can be used to place the sensor's optics in small spaces, or to detect very small objects.

An optical fiber is composed of cylindrical glass (or a plastic core), surrounded by Teflon or Silicon coating. The difference between the core and the coating refraction indexes allows the light to be diffused inside the fiber in a guided manner. The coating is covered by a plastic or metal sheath, which has an exclusively mechanical protection function. Fibers with a glass core and metal sheath are suitable for very high temperature uses, or for particular mechanical requirements. Plastic fibers, offering great adaptability, are the most diffused in all

PLCs

IDEC

applications. Plastic optic fibers have a standard 2.2mm external diameter and generally have a cylindrical threaded metal head on the end used for mechanical mounting. These fibers are usually 1 and 2 meters in length as reductions in performance become significant with lengths over 5 meters. Plastic optic fibers can be shortened using a special fiber-cutting tool, but, it can only be used a limited number of times. Cutting the fiber with a non-sharp or non-perpendicular blade will reduce operating distance. High temperature, extra-flexible or high efficiency plastic optic fibers are also available.



#### **Laser Sensors** A LASER (Light Amplification by Stimulated Emission of Radiation) is

Automation Software

Power Supplies

Sensors

**Communication & Networking** 

very small objects or to reach very long operating distances. With reference to the safety of laser radiation (according to the EN60825-1 European standard) class 1 requires that the laser device is safe under

uíín \*

reasonable operating conditions and is not dangerous for people in any situation; while class 2 states that the eye cannot be protected just by looking away or blinking, thus precautions must be adopted to avoid staring into the beam.



**IMPORTANT:** Always consider safety when installing a laser sensor of any kind. Make sure that the laser beam cannot inadvertently shine into the eyes of people passing by or working in the vicinity. See safety information on page 232.

an electronic device, such as a diode, that converts an energy source

into a very thin and concentrated light beam, suitable for detecting

# Mounting

Mounting brackets and hardware are included with sensors, where applicable. Use the hardware for mounting, along with washers and spring washers or lock nuts. Do not overtighten hardware. Overtightening causes damage to the housing and will adversely affect the waterproof characteristics of the sensor.

Best results can be obtained when the sensor is mounted so that the object sensed is in the center of the beam, rather than when the object is located near the edges of the sensing window. In addition, the most reliable sensing occurs when the majority of the objects being sensed are well within the sensing range, rather than at the extreme near and far limits.

# Wiring

Avoid running high-voltages or power lines in the same conduit with sensor signal lines. This prevents inaccurate results or damage from induced noise. Use a separate conduit when the influence of power lines or electromagnetic equipment may occur, particularly when the distance of the wiring is extended.

**IMPORTANT**: Connect the sensor cables and wires as noted in the individual Wiring sections. Failure to connect as shown in wiring diagrams will result in damage to the internal circuit.

When extending sensor cables and wires, make sure to use cables equal or superior to that recommended in the individual specifications sections.

When wiring terminals, be sure to prevent contact between adjoining terminals. When using ring or fork lug terminals, use the insulated sleeve style only. Each sensor terminal can accept only one ring or fork lug terminal.

## **Power Supply**

Noise resistance characteristics are improved when a sensor is grounded to the OV power terminal. If the OV power terminal is not at ground potential, use a ceramic 0.01µF capacitor which can withstand 250V AC minimum.



When using a switching power supply, be sure to ground the FG terminal to eliminate high-frequency noise. The power supply should include an insulating transformer, not an autotransformer.

The compact PS5R-A power supply is the perfect companion item for most IDEC sensors. This power supply is only 1.77" (45mm) wide, 3.15" (80mm) tall, and 2.76" (70mm) deep. Call an IDEC representative for more details.

Part Number	Output Ratings
PS5R-A12	12V DC, 0.62A
PS5R-A24	24V DC, 0.32A

#### **Miscellaneous**

Strong magnetic fields may detract from the accuracy of the sensing measurements. Avoid mounting a sensor directly to machinery, since the housing is connected to the electronic circuit ground of the sensor. If it is necessary to mount a sensor on machinery, use the insulating plate and sleeve provided.

# Sensors

#### Glossary

**Attenuation**: Reduction of beam intensity as a result of environmental factors such as dust, humidity, steam, etc.

**Dark on**: Output energized when light is not detected by the receiving element. For through-beam sensors, light from the projector is not detected by the receiver when an object is present. For reflected light sensors, light is not detected when it is not reflected from an object surface.

**Diffuse-reflected light sensors**: Sensors that detect all scattered and reflected light. Light reflected from nearby surfaces, as well as the intended object surface, is detected. Diffuse-reflected light sensors are often called "proximity switches," since they switch when any object is near. Also use to detect color contrast when colors reflect light intensity differently (green LED recommended for this application).

**EEPROM**: Acronym which stands for electronically erasable, programmable, read only memory.

**Excess gain**: Ratio of optical power available at a given projector-to-receiver range divided by the minimum optical power required to trigger the receiver.

**Extraneous light**: Incident light received by a sensor, not related to the presence or absence of an object being detected. Extraneous light is usually unwanted background light such as sunlight and incandescent lamps in close proximity.

 $\Delta E$ : The measurement of color difference as a three-variable function, located on an XYZ axis of light, hue, and chroma values.

**Hysteresis**: The lag in response shown by an object in reacting to changes in the forces affecting it . Operating point and release point at different levels. For solid state sensors, this is accomplished electrically. For mechanical switches, it results from storing potential energy before the transition occurs.

**Light on**: Output energized when light is detected by the receiving element. For through-beam sensors, light from the projector is detected by the receiver when an object is not present. For reflected light sensors, light is detected when it is reflected from an objects surface.

**Linearity**: The measure of the extent to which a certain response is directly proportional to the applied excitation.

**NPN/PNP**: Types of open collector transistors. NPN is a sink transistor; output on establishes negative potential difference. PNP is a source transistor; output on establishes positive potential difference.

**Polarizing**: Filtering out all reflected light except that which is projected in one plane only. Polarized retro-reflected light sensors detect the light from corner-cube type reflectors when an object is not present.

**Reflected-light sensors**: Sensors with the projector and receiver in one housing. Light is projected by the light source, and reflected light is received by the optical surface. Includes diffuse-reflected, retro-reflected, limited-reflected, and spot-reflected sensors.

**Repeatability**: Ability of a sensor to reproduce output readings consistently when the same value is applied consecutively, in the same direction, for a specified number of cycles, or for a specified time duration.

**Resolution**: Overall dimension of the smallest object which can be detected (when sensing the presence of an object) or smallest increment of distance which can be distinguished with reliable results (when sensing the position of an object).

**Response time**: Time elapsed between input and output. Total response time is the sum of object detection, amplifier response, and output response times.

**Retro-reflective**: This type of reflected light sensor uses a special reflector to return projected light when an object is not present. Sensor detects the presence of an object when the light is reflected differently.

**Through-beam sensors**: Sensors with a separate projector and receiver. The light source from the projector is detected by the receiver, except when an object is present.

**Transient**: Undesirable surge of current (many times larger than normal current) for a very short period, such as during the start-up of an inductive motor.

PLC