
	PSA-600xx (1 Phase)			
022200	Specifications			
O Mack Corp.				
	ROHD (II)	(6 11		
Switching Proper Supply Get No. (PSS-18034	(U) 🚳	66 5		
Cal No. Pala Management	usres .		The state of the s	
_ \				
MR DA UP				
	1			
MODEL	DC VOLTAGE	PSA-60024	PSA-60048 (only on request)	
	RATED CURRENT	24 V 25 A	48 V 12A	
	CURRENT RANGE	Refer to Output derating curve	IEN.	
	RATED POWER	600 W	600 W	
	The street of th	100 mVp-p	100 mVp-p	
	RIPPLE & NOISE (max)		using a 12" twisted pair-wire terminated with a 0.1µF & 47µF	
	VOLTAGE ADJ. RANGE	22 V – 27 V	41 V – 55 V	
	VOLTAGE TOLERANCE	-0.1 Tolerance: includes set up tolerance, line regulation and	POPULATION OF THE PROPERTY OF	
	START UP WITH STRONG LOAD	≤ 50,000 µF	soad regulation. ≤ 50,000 μF	
	CURRENT SHORT CIRCUIT Icc	60 A	30 A	
	Max 2 sec.: Hiccup mode			
	Permanent: Continuous mode			
	DISSIPATION POWER LOAD mas	54 W	54 W	
	LINE REGULATION LOAD REGULATION	± 0.5% ± 1%	± 0.5% ± 1%	
	LOAD REGULATION	1 sec. (max)	1 176	
	SETUP, RISE TIME	A STAN A CONTRACT OF THE STAN A CONTRACT OF T	ning ON/OFF the power supply may lead to increase of the set up	
OUTPUT	HOLD UP TIME (Typ.)	Typ. 20 msec		
		90 - 135V AC / 180 - 264V AC by switch		
	VOLTAGE RANGE		ż	
	FREQUENCY RANGE	47 – 63 Hz +-6%		
	EFFICIENCY (Typ.) AC CURRENT (115 – 230 Vac.)	>91 % 8 – 4.2 A		
	INRUSH CURRENT (Typ.)	< 16 A < 5 msec		
	INTERNAL FUSE	T 10 A		
	EXTERNAL FUSE (recommended)	16 A (curve B)		
PROTECTION	LEAKAGE CURRENT	< 1.5 mA @ 230 Vac		
		In (60°C) x 1.5 ° 3 min.; Current max. Overload ≅ 4Vdc (permanent) Imax=In (60°C) x (1.8 - 2.2)		
	OVERLOAD	Surrent max. Overload = 4700 (permanent) max-m (00 °C) x (1.0 ° 2.2)		
	OVEREGAD	30 - 35 Vdc	50 - 55 Vdc	
	OVER VOLTAGE			
		Yes. Shuts down output and automatically restarts when	the temperature inside goes down	
	OVER TEMPERATURE			
	CHART CIRCUIT PROTECTION	1 Hiccup Mode	-	
	SHORT CIRCUIT PROTECTION	2 Fold Back 3 Restart After Main		
FUNCTION	DC OK AKTIV SIGNAL (max.)	20 – 30 Vdc	40 – 55 Vdc	
(N) TO TO 170 (170)	WORKING TEMP.	-25 up to +70 °C	1.05 2000000	
	Minuser sand was related to the control of the cont	(>60°derating 2.5% °C)		
	HUMIDITY	95 % at 25°C, no condensation		
	STORAGE TEMP TEMP. COEFFICIENT	-40 up to +85 °C ± 0.03% / C° (0 – 60 °C)		
ENVIRONMENT	VIBRATION	± 0.03% / C* (0 = 60 °C) In according to IEC60068-2-6		
SAFETY &	SAFETY STANDARDS	UL508 approved,	NOT UL-APPROVED	
EMC		IEC/EN 60950, EN 50178, IEC/EN 60950, EN60950-1,	PELV EN 60204-1	
	WITHSTAND VOLTAGE	I/P-O/P: 3k VAC I/P-FG: 1.6k VAC O/P-FG: 500 V/	AC .	
	PROTECTION CLASS	IP 20		
	(EN/IEC 60529) ISOLATION RESISTANCE	100 MΩ (min) @ 500 Vdc		
	EMI CONDUCTION & RADIATION	EN61000-6-4		
	HARMONIC CURRENT			
		EN 61000-4-2, EN 61000-4-3, EN 61000-4-4, EN 61000	9-4-5,	
		EN 61000-4-6, EN61000-6-2, EN61000-6-4,	AND AND A SECOND WITH A SECOND	
	EMS IMMUNITY		be installed into a final equipment. The final equipment must be re-	
	MTBF IEC 61709	> 500.000 h		
	POLLUTION DEGREE	2		
	CONNECTION TERMINAL BLOCK DIMENSION	4 mm Screw (30 – 10 AWG)		
	PACKING	85x120x140 mm (3.34x4.72x5.51 in) 0.75 kg (1.9 lbs) per 1 pcs		
	F-790X-0803F-704C	All parameters NOT specially mentioned are measured	1000110: 1 1111 1 1000 1 1: 1	
OTHERS	NOTE	All balances INO Labellally mentioned are measured	at 230V AC input, rated load and 25 C of ambient temperature	

Terminal Pin, No Assign. (TB1)

Pin No. Assignment PSA-600xx (1 phase)

1 L
2 N
3 Jumper 115V AC
4 Jumper 115V AC
5 FG


Pin No.	Assignment	
1,2	DC output -V	
3,4	DC output +V	
5.6	DC OK relay contacts	




DC OK Relay Contact

Outputs are used for preventive function monitoring of the power supply. An electrically isolated signal contact is available. The signal contact closes

when the output power is OK and opens when the output voltage falls below 20Vdc ±5%.



Output Derating Curve



Parallel Connection

A parallel connection with the same model power supply can be set up to increase the output power.

The output has to be adjusted approximately to the same value (± 20mV) while applying a 1-2 A load to all devices before connecting them in parallel.

In PSA-600xx, for more power, the position of the Easy Parallel jumper needs to be changed to enable a parallel connection. In this mode up to 4 power supplies can be put together in parallel.

